

NORTHFIRE COMPLIANCE


Service & Compliance Record

Hood, canopy, duct & rooftop fan cleaning — NFPA 96 / CAN-ULC-S649

SAMPLE — FOR ILLUSTRATION ONLY. NOT AN ACTUAL SERVICE RECORD.

LOCATION	SERVICE DATE
Sample Kitchen, Greater Toronto Area	[Sample Date]
SERVICE TYPE	KITCHEN VOLUME TIER
Hood, canopy, plenum, duct & rooftop fan cleaning	High volume — quarterly (NFPA 96)
PRE-SERVICE DEPTH-GAUGE READING	POST-SERVICE DEPTH-GAUGE READING
0.15 in — exceeds the 0.078 in NFPA 96 / CAN/ULC-S649 cleanliness threshold	0.00 in — bare metal confirmed
STRUCTURAL CHECK (DUCT ACCESS PANEL, FAN HINGE KIT)	NEXT SERVICE DUE
Pass — no blockers found	[Sample Date + 3 months]
GREASE-TRAP HAULER MANIFEST	TECHNICIAN
On file — see compliance binder tab 2	Northfire Compliance crew

PHOTO DOCUMENTATION



This record certifies that the above-described exhaust system was cleaned to bare metal and measured against the CAN/ULC-S649 cleanliness threshold (0.078 in). Northfire Compliance is not affiliated with, certified by, or endorsed by NFPA, ULC, or IKECA — this document reflects our own internal service and documentation standard, not a third-party certification.

Authorized by: _____

Date: _____